

FIG. 1
(Prior Art)




FIG. 2
(Prior Art)




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8

FIG. 9 is a schematic diagram of a user interface for a measurement tool. The interface includes a top menu bar with options: File, View, Interface, Measurements, Tools, Window, and Help. Below the menu bar is a toolbar with icons for various functions. The main content area is divided into four horizontal sections: 266, 267, 268, and 269. Section 266 is the top section, followed by 267, 268, and 269 at the bottom. The interface is labeled 83, 247, 245, 249, 266, 267, 268, and 269.




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20A




FIG. 20B




FIG. 21

FRAME BUFFER SEQUENCE	0L	0R	1L	1R
IMAGE SEQUENCE	1	2	3	4

FIG. 22




FIG. 23

FRAME BUFFER SEQUENCE	0L	0R	1L	1R
IMAGE SEQUENCE	1		2	

FIG. 24